Scope of	Work for Property Loc	ated a	t:		3835 North 28th Street	<u>t</u>	
	Property is: Single Fan	nily 🗵	Du	ıplex	☐ Other ☐		
Date:	2/25/2014						
take no respo	onsibility for problems discovered	after the i	nspect	ion da	-	evelopment Authority, and their repor oversight. The list does not necens.	
Exterior	Condition Report						
Location Site	Required Work Landscaping	n/a ⊡	Ye	s 🔲	Note/Comments Self Help	\$	Cost
	Steps/Handrails	n/a ⊡	Ye	s 🗌		\$	
	Service walks	n/a [Ye	s 🗸	Repair	\$	200.00
	Fencing	n/a ⊡	Ye	s 🗌		\$	
	Parking	n/a ⊡	Ye	s 🗌		\$	
	Retaining walls	n/a ✓	Ye	s 🗌		\$	
	Other	n/a	Ye	s 🗆		\$	
	Other	n/a	Ye	s 🗌		\$	
Garage	Singles: repair	n/a	Ye	s 🗌		\$	
	Shingles: Roof over existing	n/a	Ye	s 🗌		\$	
	Shingles:Tear off & re-roof	n/a	Ye	s 🗌		\$	
	Gutters/downspouts	n/a	Ye	s 🗌		\$	
	Flashing	n/a	Ye	s 🗌		\$	
	Eaves	n/a	Ye	s 🗌		\$	
	Siding	n/a	Ye	s 🗌		\$	
	Doors	n/a	Ye	s 🗌		\$	
	Windows	n/a	Ye	s 🗌		\$	
	Slab	n/a	Ye	s 🗌		\$	
	Paint	n/a	Ye	s 🗌		\$	
	Electrical	n/a	Ye	s 🗌		\$	
	Other	n/a	Ye	s 🗌		\$	
Porches	Roof	n/a ☑	Ye	s 🗌		\$	
	Deck-upper	n/a ⊡	Ye	s 🗌		\$	
	Decklower	n/a ☑	Ye	s 🗌		\$	
	Steps/handrails	n/a ☑	Ye	s 🗌		\$	
	Ceiling	n/a [✓	Ye	s \square		\$	
	Guardrails	n/a	Ye	s 🗸	Repair	\$	150.00
	Structural	n/a [✓	Ye	s \square		\$	
	Paint	n/a	Ye	s 🗸	Floor, rails, ceiling	\$	250.00

n/a $\ \square$ Yes $\ \boxdot$ Make ext light code compliant

\$

150.00

Other

House

Chimney	n/a ☑ Yes □	\$
Shingles: repair	n/a ☐ Yes ☑	\$ 750.00
Shingles: Roof over existing	n/a ☑ Yes □	\$
Shingles:Tear off & re-roof	n/a ☑ Yes □	\$
Gutters/downspouts	n/a ☑ Yes □	\$
Flashing	n/a ☑ Yes □	\$
Eaves	n/a ☑ Yes □	\$
Siding	n/a 🗌 Yes 🗹 Repair	\$ 150.00
Storm Doors	n/a ☑ Yes □	\$
Prime ("main") Doors	n/a 🗌 Yes 🗹	\$ 350.00
Storm Windows	n/a ☑ Yes □	\$
Prime ("main") Windows	n/a ☑ Yes □	\$
Paint	n/a Yes Trim and foundation	\$ 1,000.00
Foundation	n/a ☑ Yes □	\$
Electrical	n/a ☑ Yes 🗌	\$
Other	n/a 🗌 Yes 🗹 repair rear window trim	\$ 150.00
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗍	\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

3,150.00

Interior Co	ondition Report						
	Unit: Entire unit (single family)					Lower unit of duplex	
Mechanical	Upper unit of duplex Required Work					Other	
Heating	Required Work						
_	Repair/replace boiler	n/a	V	Yes			\$
	Repair radiation	n/a	V	Yes			\$
	Repair/replace furnace	n/a	V	Yes			\$
	Repair ductwork	n/a	V	Yes			\$
	Replace thermostat	n/a	V	Yes			\$
	Repair/replace grilles	n/a	V	Yes			\$
	Tune boiler/furn. insp ht exchang	ı n/a	V	Yes			\$
Electrical	Repair/replace receptacles	n/a	~	Yes			\$
	Repair/replace switches	n/a	V	Yes			\$
	Repair/replace fixtures	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Upgrade service	n/a	V	Yes			\$
	Other	n/a		Yes			\$
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a	V	Yes			\$
	Repair/replace kitchen sink fauce	: n/a	V	Yes			\$
	Repair/replace tub	n/a	V	Yes			\$
	Repair/replace tub faucet	n/a	V	Yes			\$
	Repair/replace toilet	n/a	V	Yes			\$
	Repair/replace lavatory	n/a	V	Yes			\$
	Repair/replace lavatory faucet	n/a	~	Yes			\$
	Repair/replace wash tub	n/a	V	Yes			\$
	Repair/replace wash tub faucet	n/a	V	Yes			\$
	Unclog piping:	n/a	~	Yes			\$
	Repair drain/waste/vent piping	n/a	✓	Yes			\$
	Repair water piping	n/a	V	Yes			\$
	Repair/replace water heater	n/a	~	Yes			\$
	Other	n/a		Yes	V	Tub Surround	\$ 350.00

Other

n/a ☐ Yes ☐

Windows									
	Replace broken glass	n/a	V	Yes			\$		
	Repair or replace sash	n/a	V	Yes			\$		
Doors	Danair ar raplace decre	n/a	V	Vaa			¢		
	Repair or replace doors	n/a	V	Yes	<u> Ц</u>		\$		
Walla/Cailina	Repair or repl. locks/latches	n/a	✓	Yes		Self Help	\$		
Walls/Ceiling	Repair or repl. @ defective	n/a		Yes	1		\$	750.00	
Paint									
	Repair or repl. @ defective	n/a	V	Yes			\$		
Fire Safety									
•	Install smoke/CO alarm:bsmt.	n/a		Yes	V	Self Help	\$	50.00	
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	50.00	
	Install smoke/CO alarm: 2nd flr.	n/a	П	Yes	V	Self Help	\$	50.00	
Handrails						·			
04-1	Repair/replace defective	n/a		Yes	√	All stairs interior	\$	250.00	
Stairs	Repair defective	n/a	V	Yes			\$		
Floors									
Other	Repair defective	n/a	V	Yes			\$		
		n/a		Yes			\$		
		n/a		Yes			\$		
		n/a		Yes			\$		
		n/a		Yes			\$		
						Interior: Estimated Cost:	\$	1,500.00	
						Total Exterior and Interior Cost:*	\$	4,650.00	
	*average contracted cost. Actual costs may vary. Self help will reduce the amount.								

Inspected by: Andy Yeager Date: 2/25/14

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.